


## Touchkit program express calibration step

### 1. Click and execute the touchkit program



### 2. Press tools tab and 4 points calibration option



### 3. Press the blinking X symbol to calibrate

Press the blinking X Symbol until stop blinking.



### 4. Press OK to complete calibration

